



Collarines Bisagra PPFV

Collarín reparación ITEM 141

REFERENCIA	DESCRIPCIÓN	Peso neto	Volumen (m ³)	Peso bruto	Unidades lote
1005050	COLLARIN BISAGRA REPARACION 225	2.67	0.044603	3.331	2
1005051	COLLARIN BISAGRA REPARACION 250	3.635	0.04836	7.94	2
1005052	COLLARIN BISAGRA REPARACION 315	6.8197	0.048799	7.395	1
1005053	COLLARIN BISAGRA REPARACION 200	2.484	0.044603	5.798	2
1005054	COLLARIN BISAGRA REPARACION 400	6.125	0.063473	6.925	1
1005055	COLLARIN BISAGRA REPARACION 160	3.11325	0.03648	6.98	2



Pol. Ind. Plá Vallonga,
c/ Agua, 28
03006 ALICANTE (España)



+34 965 11 42 82



+34 965 11 48 62




tecnicocomercial@hidroten.es



Servicio Atención
Técnica comercial
+ 34 966 105 888



www.hidroten.es




ITEM 141 | Collarín reparación

CÓDIGO	f tubo	PESOS	A	B	C	PN	MEDIDA
05055	160	2535	160	225	186	PN6	MÉTRICO
05053	200	2484	200	227	226	PN6	MÉTRICO
05050	225	2717	225	225	250	PN6	MÉTRICO
05051	250	3096	250	239	276	PN6	MÉTRICO
05052	315	4398	315	250	344	PN6	MÉTRICO
05054	400	6125	400	282	430	PN6	MÉTRICO





Documentación de Producto



Certificados de Producto

Certificados de Empresa



Pol. Ind. Plá Vallonga,
c/ Agua, 28
03006 ALICANTE (España)



+34 965 11 42 82



+34 965 11 48 62



tecnicocomercial@hidroten.es



Servicio Atención
Técnica comercial
+ 34 966 105 888



www.hidroten.es